

# Effective cleaning with Clinell Universal Wipes

Clean all surfaces and equipment between every patient use.



1



Use one wipe at a time, wipe in an “S” Shape pattern to cover entire area.

2



Allow to air dry for one minute.

3



Once the wipe is dry or soiled, throw it out and replace with a new one.

4



Do not rewet the wipe or use the same wipe on multiple pieces of equipment.

\* Please ensure that you follow the equipment manufacturer's guidelines.